

## PHAP14-00033

Date: December 8, 2014

**Application Type:** Certificate of Appropriateness

**Property Owner:** Celia Peinado

**Representative:** Modern Exteriors of El Paso

Legal Description: Being11 Manhattan Heights 46 and 47, City of El Paso, El Paso County,

Texas

Historic District: Manhattan HeightsLocation: 816 Magoffin Avenue

Representative District: #2

**Existing Zoning:** R-3/H (Residential/Historic)

Year Built: 1916


Historic Status: Contributing

**Request:** Certificate of Appropriateness for the removal of exterior stucco and

wood on second floor, fasciae, and soffits and replacement with vinyl

**Application Filed:** 11/26/2014 **45 Day Expiration:** 1/10/2015

## ITEM #2



### **GENERAL INFORMATION:**

The applicant seeks approval for:

Certificate of Appropriateness for the removal of exterior stucco and wood on second floor, fasciae, and soffits and replacement with vinyl

## **STAFF RECOMMENDATION:**

The Historic Preservation Office recommends APPROVAL WITH A MODIFICATION of the proposed scope of work based on the following recommendations:

The Design Guidelines for El Paso's Historic Districts, Sites, and Properties recommend the following:

- If areas are deteriorated beyond repair they should be replaced in kind to match the original historic material compounds. Aluminum, vinyl, plywood or other synthetic sidings shall be reviewed by the HLC. However, some may be considered on an individual basis if the proposed material matches the existing historic material, all original detailing is left exposed, window and door trim are not covered, and any unique finishes are intact and not covered or damaged.
- Preservation, restoration, or reconstruction of a structure's original fixtures is recommended. Source and select original materials and employ traditional construction methods as per preservation briefs or historic specifications.
- If it is necessary to replace masonry, always use materials that match the color, size and texture of the masonry being replaced.
- Preserve the shape, size, materials, and details of character-defining chimneys and foundations and other masonry/stone features.

The Secretary of the Interior's Standards for Rehabilitation recommend the following:

• When the severity of deterioration requires replacement of a distinctive feature, the new feature will match the old in design, color, texture, and where possible materials.

The modification is that the fasciae and soffit be replaced with vinyl but that the exterior stucco be replaced with stucco to match the existing or that insulation be placed on the interior so that the exterior character is not altered or affected.



## **SPECIFICATIONS**

#### Modern Exteriors of El Paso

13320 Tobacco Rd \* El Paso, Texas 79938 (915) 857-5126 \* Fax (915) 857-0228 modern exteriors@att.net

STYROFOAM Extruded Polystyrene Foam Board Insulation (Common: .75-in x 4-ft x 8-ft; Actual: 0.687-in x 3.937-ft x 7.875-ft)



- Lightweight and east to handle Helps manage energy loss and moiste Easy to cut Reduces moisture in your home

<ul> <li>Insulation Type</li> </ul>	Extruded polystyres
R-Value	4
Actual Length (Feet)	7.875
Actual Thickness (Inches)	0.687
Actual Width (Feet)	3.937
Common Length (Feet)	8
Common Thickness (Inche	s) 0.75
Common Width (Feet)	4

# Ventura<sup>o</sup> Hidden Vent Soffit

# Fredrei Code/Deresigites

Brokel 647 Test 





## Solut Sealisting

Adres Iberal One Resign 

## Board + Batten Designer Series"

Product Code/Description



#### Color Availability